

JV34-260 & TS34-1800A firmware version 1.50 has been released.

Feb 20, 2013

Changes

Update version	Current version
1.50	1.40

1. Changing the below contents.

No	Contents
1	Deep Black has been added to Sb53 ink. (I-SB53-DK-2L-1, I-SB53-DK-44-1)
2	The maximum value of the "INTERVAL" setting of [AUTO CLEANING] function and [Print. CLEANING] function has changed from 10m to 30m.
3	The "STOP TIME" setting of [DRY FAN] function became able to change by 1 minute.

2. Improvement of the below-shown defects.

No	Contents
1	The freeze may occur rarely when print is started.
2	In case of it takes a time to print starting in the [TEST PRINT], you will have a misunderstanding as the machine has been freezing because the LCD display is no change.
3	TS34 does not have the cleaning cartridge but, the warning "WashLiquidCart.NONE" is recorded in the Log of the error history.

Special Instruction

When the first power-on after the upgrade, Maintenance parameter, Ink system parameter, Ink information parameter, Ink sequence parameter, Ink type parameter, Servo parameter and Test parameter are automatically initialized.